Recreational Use Survey Summary								
Survey Location	Representative Site Photo	Channel Characteristics	Land Use Conditions	Equipment Installed	Survey Start Date	Survey End Date	Number of Images Collected	
Vertical Channel								
Greenville Banning Channel at Adams Ave		Concrete lined, vertical walled channel	Residential and open space	Camera - Observer IV, External Battery	11/17/2005	1/3/2006	2,552	
Greenville Banning Channel at Pedestrian Bridge		Concrete lined, vertical walled channel	Residential and Vacant Natural Land	Camera - Observer IV, External Battery	7/7/2005	7/27/2005	425	
Santa Ana Delhi Channel at Mesa Ave		Concrete lined, vertical walled channel	Residential / Open Space and Recreation	Camera - Observer IV, External Battery	6/20/2005	7/13/2006	21,284	
Cucamonga Creek at IEUA		Concrete Lined / Vertical Walled Channel	Industrial/commercial and Open Space/recreation	Camera - Observer IV, External Battery	10/2/2007	10/10/2008	27,122	
Anza Channel at John Bryant Park		Concrete Lined / Vertical Walled Channel	Residential and open space/ public park	Camera - Observer IV, Solar Panel, External Battery	6/6/2008	ongoing	3,400	
Demens Channel		Concrete Lined / Vertical Walled Channel	Residential and open space	Camera - Observer IV, External Battery	2/1/2008	ongoing	15,619	

Recreational Use Survey Summary								
Survey Location	Representative Site Photo	Channel Characteristics	Land Use Conditions	Equipment Installed	Survey Start Date	Survey End Date	Number of Images Collected	
Trapezoidal Channel								
Cucamonga Creek at Hellman Ave (Upstream)		Trapezoidal channel, concreted lined wall and bottom	Agriculture	Camera - Observer IV, External Battery	11/1/2005	11/1/2006	2,546	
Temescal at Main Street		Trapezoidal channel, concreted lined wall and bottom	Industrial / Commercial	Camera - Observer IV, External Battery	7/26/2005	8/4/2005	513	
Temescal at City of Corona WWTP No. 2		Trapezoidal channel, concreted lined wall and bottom	Industrial / Commercial	Camera - Observer IV, Solar Panel, External Battery	11/1/2005	11/1/2006	10,653	
Santa Ana Delhi Channel at Sunflower Ave		Trapezoidal channel, rip rap side slopes, natural bottom	Commercial/ residential/ school	Camera - Observer IV, External Battery	7/7/2005	7/9/2006	20,978	
Cucamonga Creek at Hellman Ave (Downstream)		Trapezoidal channel, rip rap side slopes, natural bottom	Agriculture	Camera - Observer IV, External Battery	7/26/2005	11/1/2006	17,678	
Perris Valley Channel at Moreno Valley WRF		Trapezoidal Channel / concrete lined side slope and concrete/natural bottom	Industrial/ Residential/school and open space/public park	Camera - Observer IV, Solar Panel, External Battery	10/3/2007	10/10/2008	21,962	

Recreational Use Survey Summary									
Survey Location	Representative Site Photo	Channel Characteristics	Land Use Conditions	Equipment Installed	Survey Start Date	Survey End Date	Number of Images Collected		
	Trapezoidal Channel (continued)								
SAR at Anaheim		Trapezoidal Channel / Rip rap side slopes and natural bottom	Industrial/ commercial and open space/public park	Camera - Observer IV, External Battery	10/2/2007	10/5/2008	25,904		
Chino Creek at Central Ave		Trapezoidal Channel / Rip rap slope and bottom	Industrial / commercial	Camera - Observer IV, Solar Panel, External Battery	12/19/2007	ongoing	12,387		
San Diego Creek at Irvine		Trapezoidal Channel / Natural side slopes and bottom	Residential/commercial/school and open space	Camera - Observer IV, Solar Panel, External Battery	6/10/2008	ongoing	5,220		

Recreational Use Survey Summary								
Survey Location	Representative Site Photo	Channel Characteristics	Land Use Conditions	Equipment Installed	Survey Start Date	Survey End Date	Number of Images Collected	
Natural Channel								
Santa Ana Delhi Channel at Newport Bay		Natural channel	Open spce/ commercial	Camera - Observer IV, External Battery	6/20/2005	6/6/2006	20,203	
SAR at Yorba Linda		Natural channel	Residential / Open space	Camera - Observer IV, External Battery	4/11/2006	4/6/2007	12,645	